



Check Union

The **BDWS Ball Check Union** is designed to seal off well pressure in the event of the wireline parting from the toolstring.

The steel ball is forced against the seat by the well pressure and sealed off, thus preventing flow from below.



Valve Check Union

The **BDWS Valve Check Union** is designed to seal off well pressure in the event of the wireline parting from the toolstring.

The valve is forced against the seat by the well pressure and seal off, thus preventing flow from below.

